



TOGETHER  
WE INCREASE

FOLLOW US






# LIQUIDATION ONLINE ASSET DISPOSAL AUCTION: TRUCKS, TRAILERS & OTHER VEHICLES - MIDDELVLEI,GP




Starting From: 22 Apr 2024 | Ending From: 30 Apr 2024




Your auction leader is: Renet Fouche (061 826 6103 / Tom: 063 505 4098 /087 728 2290)




For online assistance contact: +27(0) 51 445 2031

To register for this Auction [Click here](#)

Lot #	Lot Item Heading	Photo	Description	Starting Bid
1	1984 Intern Harvester S-Line Horse		<p>1984 Intern Harvester S-Line Horse The overall condition is poor for the exterior and interior. The engine appears to be complete but could not be test...</p>	R 10000.00
2	1983 Intern Harvester S-Line Horse		<p>1983 Intern Harvester S-Line Horse This S-Line offers a sleeper bunk. The Truck is fitted with a bull bar. The overall condition is poor. The cab is ol...</p>	R 15000.00
3	1995 Isuzu KB Series		<p>1995 Isuzu KB Series The engine is partially stripped and the LDV has been standing for a long time in the open. The Body show signs of rust and has va...</p>	R 2500.00

4	1987 Isuzu FVZ1400 Turbo 6x4		<p>1987 Isuzu FVZ1400 Turbo 6x4 The exterior body is dented and rusted. The chassis is also bent and rusted. The paint is faded and the steps are cracked a...</p>	R 15000.00
5	1996 LCM Load Trailer		<p>1996 LCM Load Trailer The Load trailer drop-sides are bent and damaged. Body has visible dents all round. The grooves on the tires appear to be in fair...</p>	R 2500.00
6	1990 LHL Trailer		<p>1990 LHL Trailer The Trailer is rusted and the tires are worn. Taillights and number plate faded.</p>	R 10000.00

7	2010 Mahindra XYLO Panel Van		<p>2010 Mahindra XYLO Panel Van The SUV is partially stripped with missing panels. The bumper is broken and the right door is dented and the trimming stri...</p>	R 2500.00
8	1989 MAN 30-365 Truck		<p>1989 MAN 30-365 Truck The Cab show visible signs of body dents, paint cracked and rusted. The interior is dirty and the seats are torn. The engine appe...</p>	R 20000.00
9	2002 Mitsubishi Pajero		<p>2002 Mitsubishi Pajero The engine has been removed and is stripped. There is no ignition key. The interior seats are dirty, cracked and torn. The exter...</p>	R 5000.00

10	2005 Road Hog Trailer Tri Axle Flatdeck		<p>2005 Road Hog Trailer Tri Axle Flatdeck The Trailer is rusted and used. The tires are poor. The trailer board is bent. The taillights are broken and so...</p>	R 15000.00
11	2006 TATA SFC407/31 2 Ton Truck		<p>2006 TATA SFC407/31 2 Ton Truck The truck is listed as a non runner as we would not test it. All appears to be in order with the engine. The gearbox kn...</p>	R 15000.00
12	1987 Toyota Hino SHB33-N3		<p>1987 Toyota Hino SHB33-N3 The truck exterior in overall poor condition. The bumper is dented and the panels rusted. The interior is in a poor condition...</p>	R 15000.00